AMENDMENTS TO THE DRAWINGS

The drawings have been amended to correct minor labeling errors.

- FIG. 7: the reference number for the block labeled "PFD" has been changed from "80" to --25--.
- FIG. 11: the label on the line connecting to M1 has been changed from "Vtb" to --Vfb--.
- FIG. 14: the MOS switch connected to "Trimstart" has been labeled --M10--.
- Three (3) replacement drawing sheets are enclosed.